

EVERYTHING NEEDED FOR AXLE EYE REPAIR

Only the STEMCO[®] Axle Pro Equipment[™] (APE) package offers everything needed to enhance worn axle eyes. This revolutionary piece of equipment comes with mounting brackets, a magnetic-based drill, coolant and safety equipment. When looking for an affordable, simple and quick way to enhance worn axle eyes, choose the STEMCO APE.

COMPLETE

APE's universality allows customization to best suit shop needs and contains all components needed to enhance worn axle eyes.

FAST

Repairs can be made without removing the axle to be able to enhance the axle eyes in just minutes.

VALUABLE

APE's mobility enables axle repairs to be made outside the shop, allowing for a quick return on investment.

DURABLE

Proven revolutionary system with options that allow for continuous release of new applications.

SIMPLE

Provides a simple, easy and reliable process to address worn axle eyes to assist in achieving maximum axle eye life.



Helping industry become, More Safe, More Productive and, More Sustainable.



A NEW EVOLUTION IN AXLE ENHANCEMENT

STEMCO® ADVANTAGE

Axle Pro Equipment[™] backed with STEMCO replacement parts–extending axle life and decreasing downtime.

STEMCO AXLE SLEEVES

- Prehardened for extended life
- Precut flat holes for ease of installation
- Presized to the axle easy installation

APE INNOVATION

APE's most versatile kits cover 60 axle codes.

85.999.99

Complete with base kit, 6 cutter kits, starter STEMCO sleeve selection and travel case

95.999.99

Complete with base kit, 6 cutter kits, starter STEMCO sleeve selection and shop cart



AXLE MAKE	AXLE CODE	APE MASTER KIT	PLUSKIT	QWIKKIT	APE CUTTER KIT	APE SLEEVE	SLEEVE DRIVER
DANA	EFA10F5, EFA12F4 EFA13F5, 02-AEA		70.120.05	K120E		91.120.05	
DANA	FA-118, FA-127, FA-139 FA-329, FA-337, FA-339 FA-342, FA-343 I-108, I-120, I-132, I-132S	85.120.05	70.140.09	K140I	84.120.05	91.140.09	ST70-6T
DANA	E-1000I, E-1000W, E-1200I E-1200W, E-1201I, E-1201W E-1320I, E1320W, 02-AED FF-931, FF-932, FF-933		70.122.05	K122E		91.122.05	
MERITOR	FF-934, FF-941, FF-942 FF-943, FF-944, FF-945 FG-931, FG-933, FG-941	85.122.05	70.931.12	K931L	84.122.05	92.961.12	ST70-7T
MERITOR	FG-943, FG-952, 02-ARG MFS-131015, MFS-13143 MFS-13144, MFS-141015 MFS-14143, MFS-14153A		77.931.18	KG931R		92.931.18	
DANA	E-1460I, E-1460W		70.146.05	K146E		91.146.05	
DANA	E-1002I, E-1002W, E-1202I E-1202W, E-1322I, E-1322W E-1462I, E-1462W, 02-AEZ	85.147.05	70.147.05	K147E	84.147.05	93.147.05	ST70-23T
DANA	EFA18F3, EFA18F4, EFA20F4 EFA22T, EFA24T, 02-ARU		70.180.05	K180E		91.180.05	
IMT / TMC	TMC SELF-STEER	85.700.20	70.700.20	K700T	84.700.20	92.700.20	ST70-29T
HENDRICKSON	KGS230	00.700.20	70.230.07	K230KG	84.700.20	94.230.07	5170-231
DANA	D2000F, D2200F, 02-ADY		70.201.19	K201S		93.201.19	ST70-24T
MERITOR	FL-931. FL-933, FL-941 FL-943, FL-951, FH-951 MFS-20142A MFS-161015, MFS-16122A	85.931.12	78.931.12	KH931L	84.931.12	92.931.12	ST70-12T
MERITOR	MFS-161013, MFS-16122A MFS-16143A, MFS-18143A MFS-73, 02-ARU		70.180.18	K180R	92.	92.180.18	



Helping Industry Become, More Safe, More Productive and, More Sustainable.



SCAN QR Code to view





AUSTRALIA, NEW ZEALAND & PAPUA NEW GUINEA

Customer Service 02-9793-2599 2/198 Walters Road Arndell Park NSW 2148 Australia www.stemco.com.au



Sleeve placement – alignment precision